

# HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 8/24/09  
 TIME: 8: AM  
 TIME OF BREAK: \_\_\_\_\_  
 ENGINEER: G. ABBOTT

**LOCATION:**

GPS LOCATION: 5916 STEVENSON FOREST RD

GPS: 340

**PHOTO BEFORE REPAIRS:**

Number of Pictures: \_\_\_\_\_

**SOIL CHEMISTRIES:**

| REDOX                |  | SOIL BOX RESISTIVITIES |  | pH                   |  |
|----------------------|--|------------------------|--|----------------------|--|
| (mV)                 |  | (Ohm-cm)               |  | (mV)                 |  |
| (mV)                 |  | (Ohm-cm)               |  | (mV)                 |  |
| Top of Pipe (12)     |  | Top of Pipe (12)       |  | Top of Pipe (12)     |  |
| Side of Pipe (3 / 9) |  | Side of Pipe (3 / 9)   |  | Side of Pipe (3 / 9) |  |
| Bottom of Pipe (6)   |  | Bottom of Pipe (6)     |  | Bottom of Pipe (6)   |  |
|                      |  |                        |  | Actual Soil pH       |  |

Soil Type: \_\_\_ Clay \_\_\_ Sand \_\_\_ Silt \_\_\_ Clay/sand \_\_\_ BGC\* \_\_\_ Other

**DETAILS:**

Pipe Type:  Cast Iron \_\_\_ Ductile Iron  Steel \_\_\_ PCCP \_\_\_ Plastic

Pipe Size: \_\_\_\_\_

Repair Method: 6" Clamp \_\_\_ Weld \_\_\_ Cut \_\_\_ Other


**DETAILS:**

Form of Break:  Circular \_\_\_ Longitudinal \_\_\_ Other

**DETAILS:**

**PHOTO AFTER REPAIRS:**

Number of Pictures: \_\_\_\_\_



\* BGC = blue/gray clay