

# HOWARD COUNTY: PIPE BREAKS - FIELD DATA

**DAY:** 12-8-06  
**TIME:** 9:00 PM  
**TIME OF BREAK:** 5:00 PM  
**ENGINEER:** G. Gibson

**LOCATION:**

**GPS LOCATION:** 5448 Thunderhill Road

**GPS:** 260 W+S

**PHOTO BEFORE REPAIRS:**

Number of Pictures:     

**SOIL CHEMISTRIES:**

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type:  Clay  Sand  Silt  Clay/sand  BGC\*  Other

**DETAILS:**

Pipe Type:  Cast Iron  Ductile Iron  Steel  PCCP  Plastic

Pipe Size: 8"

Repair Method:  Clamp  Weld  Cut  Other

**DETAILS:**


Form of Break:  Circular  Longitudinal  Other

**DETAILS:**


**PHOTO AFTER REPAIRS:**

Number of Pictures:     

**SKETCH OF SITE**



**TESTING VIEW**



\* BGC = blue/gray clay