

Description:

The house faces southwest toward the road, on the northeast side of the road, and is set well back from the road behind a row of other houses. This is a 1 ½-story bungalow with a stuccoed foundation and walls and a gable roof with asphalt shingles and a northwest-southeast ridge. There is an ell on the rear, to the northwest, and a modern kitchen addition on the rear to the southeast, and they both have a shed roof and asphalt shingles. The southwest elevation has a front porch that was added or heavily rebuilt, and it is enclosed with jalousie windows. There is a shed-roofed dormer that was either added or heavily rebuilt, and it has aluminum siding and two one-over-one sash. The house has one room across the front and two in the back, one in the ell and one in the addition. The southwest room has a patch in the center that may have had a stair here originally. There is a straight-run stair on the southeast wall consistent with c. 1950s construction.

Significance:

The house at 10730 Scaggsville Road was probably built as a Cape Cod in the 1930s – 50s, but has been significantly altered with large shed-roofed dormers on the front and back and an enclosed porch on the front that make it similar to a bungalow. The front porch is not contained within the roof of the main block of the house, however. The interior has also seen major alterations that probably took the original stairway and changed the floor plan, and there are few historic features surviving inside. The roof has not been maintained and the building has significant rot and mold. It is scheduled to be demolished in 2009.

1. Name of Property (indicate preferred name) historic other 2. Location 10730 Scaggsville Road street and number not for publication Scaggsville city, town X vicinity county Howard 3. Owner of Property (give names and mailing addresses of all owners) Stephen & Barbara Forney name 3368 Brantly Ct 410-977-1328 street and number telephone Glenwood MD 21738 city, town state zip code 4. Location of Legal Description courthouse, registry of deeds, etc. Howard County Courthouse liber 8809 folio 407 Ellicott City tax map 46 tax parcel 12 tax ID number city, town

5. Primary Location of Additional Data

Contributing Resource in National Register District Contributing Resource in Local Historic District Determined Eligible for the National Register/Maryland Register Determined Ineligible for the National Register/Maryland Register Recorded by HABS/HAER Historic Structure Report or Research Report at MHT Other:

6. Classification

Category Ownership **Current Function Resource Count** public district agriculture landscape Contributing Noncontributing building(s) private commerce/trade recreation/culture X 0 buildings X both defense 0 structure religion 0 sites site domestic social 0 0 structures object education transportation 0 0 objects funerary work in progress 1 0 Total government unknown health care vacant/not in use Number of Contributing Resources industry other: previously listed in the Inventory 0

7. Description

Inventory No. HO-995

Condition

excellent	X deteriorated
good	ruins
fair	altered

Prepare both a one paragraph summary and a comprehensive description of the resource and its various elements as it exists today.

Summary:

The house faces southwest toward the road, on the northeast side of the road, and is set well back from the road behind a row of other houses. This is a 1 ½-story Cape Cod later altered to be similar to a bungalow, with a stuccoed foundation and walls and a gable roof with asphalt shingles and a northwest-southeast ridge. There is an ell on the rear, to the northwest, and a modern kitchen addition on the rear to the southeast, and they both have a shed roof and asphalt shingles. The southwest elevation has a front porch that was added or heavily rebuilt, and it is enclosed with jalousie windows. There is a shed-roofed dormer that was either added or heavily rebuilt, and it has aluminum siding and two one-over-one sash. The house has one room across the front and two in the back, one in the ell and one in the addition. The southwest room has a patch in the center that may have had a stair here originally. There is a straight-run stair on the southeast wall consistent with c. 1950s construction.

Description:

The house at 10730 Scaggsville Road is located about one mile east of Scaggsville in southeastern Howard County, Maryland. The house faces southwest toward the road, on the northeast side of the road, and is set well back from the road behind a row of other houses. The ground slopes down to the northwest, northeast, and southeast, and is wooded to the northeast and east. This is a 1 ½-story Cape Cod later altered to be similar to a bungalow, with a stuccoed foundation and walls and a gable roof with asphalt shingles and a northwest-southeast ridge. There is an ell on the rear, to the northwest, and a modern kitchen addition on the rear to the southeast, and they both have a shed roof and asphalt shingles. The addition covers some buff colored brick-pattern asphalt shingle siding.

The southwest elevation has a front porch that was added or heavily rebuilt, and it is enclosed with jalousie windows and has a parged foundation and a shed roof. The porch covers a modern wood crossbuck door in the west bay and a six-over-six wood sash in the south bay. There is a shed-roofed dormer that was either added or heavily rebuilt, and it has aluminum siding and two one-over-one sash. On the northwest elevation the first story has a porch that was removed from the north bay, and a new door in this opening. The west bay has an added three-sided bay window. The gable end has a wood six-over-six sash in a modern frame. The ell has a wood six-over-six sash in a modern frame. The ell has a wood six-over-six sash in a modern frame, and there is a metal vent in the foundation. The northeast elevation has stucco on the north half that could be original or early, and is probably the original kitchen. There is no opening here. The east half has a CMU foundation and aluminum siding, and this extends to the southeast end of the house. There is a shed-roofed dormer that matches the southwest elevation and also was probably rebuilt; it has a small two-over-two double-hung sash. The southeast elevation of the main block has a one-light sash in the foundation, in the south bay. The first story has a wood six-over-six sash in a modern frame in the east bay, and the gable end has a similar sash in the center.

Maryland Historical Trust Maryland Inventory of Historic Properties Form

Name Continuation Sheet

Number 7 Page 1

The house has one room across the front and two in the back, one in the ell and one in the addition. The southwest room has 2 ¹/₄-inch oak flooring that runs northwest-southeast, with a patch in the center. The northwest end of the patch is straight and aligns with the beam in the ceiling, making it appear that there was a wall here that was removed. The southeast side of the patch is ragged. The patch is about 31 inches wide and may have had a stair here originally. There is a straight-run stair on the southeast wall, with an open stringer, and it is constructed in pine. There are turned tapered balusters and newel posts that are consistent with c. 1950s-⁶70s construction, and there are oak treads. There is a stove chimney on the northeast wall, in the center. The northeast room has a bathroom added in the east corner, and this has a two-panel door. The flooring matches that in the southwest room. All of the mouldings are a modern flat ogee. There is a modern kitchen in the ell, with no historic features surviving. The second story has drywall and clamshell mouldings, with no old fixtures in the bathroom, and it appears to have been completely rebuilt. All of the sash are post World War II and are not original. There is significant leaking in the building and a lot of black mold. The building is slated to be demolished.

Inventory No. HO-995

8. Signific	ance			Inventory No. HO-995
Period	Areas of Significance	Check and justify below		
1600-1699 1700-1799 1800-1899 X 1900-1999 2000-	 agriculture archeology architecture art commerce communications community planning conservation 	 economics education engineering entertainment/ recreation ethnic heritage exploration/ settlement 	 health/medicine industry invention landscape architecture law literature maritime history military 	 performing arts philosophy politics/government religion science social history transportation other:
Specific dates	N/A		Architect/Builder N/A	
Construction da	ates			
Evaluation for:				
	National Register	N	Aryland Register	Xnot evaluated

Prepare a one-paragraph summary statement of significance addressing applicable criteria, followed by a narrative discussion of the history of the resource and its context. (For compliance projects, complete evaluation on a DOE Form – see manual.)

The house at 10730 Scaggsville Road was probably built as a Cape Cod in the 1930s – 50s, but has been significantly altered with large shed-roofed dormers on the front and back and an enclosed porch on the front that make it similar to a bungalow. The front porch is not contained within the roof of the main block of the house, however. The interior has also seen major alterations that probably took the original stairway and changed the floor plan, and there are few historic features surviving inside. The roof has not been maintained and the building has significant rot and mold. It is scheduled to be demolished in 2009.

9. Major Bibliographical References

10. Geographical Data

Acreage of surveyed property	2.7 A		
Acreage of historical setting	2.7 A		
Quadrangle name	Clarksville	Quadrangle scale:	1:24000

Verbal boundary description and justification

The boundaries consist of the property lines for tax map 46, parcel 12, which encompasses all of the historic buildings on the site.

11. Form Prepared by

name/title	Ken Short		
organization	Howard County Department of Planning & Zoning	date	September 2009
street & number	3430 Courthouse Drive	telephone	410-313-4335
city or town	Ellicott City	state	Maryland

The Maryland Inventory of Historic Properties was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust DHCD/DHCP 100 Community Place Crownsville, MD 21032-2023 410-514-7600



HO-995

10730 Scaggsville Road Clarksville quad

HO-995

10730 Scaggsville Road Howard County, Maryland Ken Short, photographer

Photo Log Nikon D-70 camera HP Premium Plus paper HP Gray Photo print cartridge

HO-0995_2009-07-08_01 Northwest & southwest elevations

HO-0995_2009-07-08_02 Southwest & southeast elevations

HO-0995_2009-07-08_03 Southeast & northeast elevations

HO-0995_2009-07-08_04 Northeast & northwest elevations



HO-995 10730 Scaggsville Read Howard County, MD. Ken Short July 8, 2009 MD SHPO Northwest & Southwest Elevations



40-995 10730 Scaggsville Road Howard County, MD Ken Short July 8, 2009 MD SHPO Southinest's Southeast Elevations



HO-995 10730 Scaggsville Rocal Howard County, MD Ken Short July 8,2009 MD SHPO Southeast & Northeast Elevations

3/4



40-995 10730 Scaggsville Rd Howard County, MD Ken Short July 8,2009 MD SHPO Northeast & Northwest Elevations