

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 9. 3. 08
 TIME: _____
 TIME OF BREAK: 7: 35
 ENGINEER: _____

LOCATION: _____
 GPS LOCATION: 6302 Taman Drive Dr and Major Lane

GPS: 374 W

PHOTO BEFORE REPAIRS:
 Number of Pictures: _____

SOIL CHEMISTRIES:

| REDOX | | SOIL BOX RESISTIVITIES | | pH | |
|----------------------|--|------------------------|--|----------------------|--|
| (mV) | | (Ohm-cm) | | (mV) | |
| (mV) | | (Ohm-cm) | | (mV) | |
| Top of Pipe (12) | | Top of Pipe (12) | | Top of Pipe (12) | |
| Side of Pipe (3 / 9) | | Side of Pipe (3 / 9) | | Side of Pipe (3 / 9) | |
| Bottom of Pipe (6) | | Bottom of Pipe (6) | | Bottom of Pipe (6) | |
| | | | | Actual Soil pH | |

Soil Type: Clay Sand Silt Clay/sand BGC* Other

DETAILS:

Pipe Type: Cast Iron Ductile Iron Steel PCCP Plastic
 Pipe Size: _____
 Repair Method: Clamp Weld Cut Other


DETAILS:

Form of Break: Circular Longitudinal Other

PHOTO AFTER REPAIRS:

Number of Pictures: _____

SKETCH OF SITE



* BGC = blue/gray clay