

# HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 11/13/09  
 TIME: 16:15 21:00  
 TIME OF BREAK: 16:15  
 ENGINEER: n/a Matt Tude

LOCATION:  
 GPS LOCATION: n/a 6525 S. Hanover Rd

GPS: \_\_\_\_\_

**PHOTO BEFORE REPAIRS:**

Number of Pictures: n/a

**SOIL CHEMISTRIES:**

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type:  Clay  Sand  Silt  Clay/sand  BGC\*  Other

**DETAILS:**

Pipe Type:  Cast Iron  Ductile Iron  Steel  PCCP  Plastic

Pipe Size: \_\_\_\_\_  
 Repair Method:  Clamp  Weld  Cut  Other

**DETAILS:**



Form of Break:  Circular  Longitudinal  Other

**DETAILS:**

**PHOTO AFTER REPAIRS:**

Number of Pictures: n/a

**SKETCH OF SITE**



\* BGC = blue/gray clay