

# HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 12-6-04  
 TIME: 2:00 pm  
 TIME OF BREAK: 1:00 pm  
 ENGINEER: G. Gibson

**LOCATION:**

GPS LOCATION: 9325 6<sup>th</sup> Street

GPS: 1-W

**PHOTO BEFORE REPAIRS:**

Number of Pictures:     

**SOIL CHEMISTRIES:**

| REDOX                |  | SOIL BOX RESISTIVITIES |  | pH                   |  |
|----------------------|--|------------------------|--|----------------------|--|
| (mV)                 |  | (Ohm-cm)               |  | (mV)                 |  |
| (mV)                 |  | (Ohm-cm)               |  | (mV)                 |  |
| Top of Pipe (12)     |  | Top of Pipe (12)       |  | Top of Pipe (12)     |  |
| Side of Pipe (3 / 9) |  | Side of Pipe (3 / 9)   |  | Side of Pipe (3 / 9) |  |
| Bottom of Pipe (6)   |  | Bottom of Pipe (6)     |  | Bottom of Pipe (6)   |  |
|                      |  |                        |  | Actual Soil pH       |  |

Soil Type:  Clay  Sand  Silt  Clay/sand  BGC\*  Other

**DETAILS:**

Pipe Type:  Cast Iron  Ductile Iron  Steel  PCCP  Plastic

Pipe Size: 6"

Repair Method:  Clamp  Weld  Cut  Other

**DETAILS:**



Form of Break:  Circular  Longitudinal  Other

**DETAILS:**

**PHOTO AFTER REPAIRS:**

Number of Pictures:     

**SKETCH OF SITE**



\* BGC = blue/gray clay