

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 11/15/09
 TIME: 1:00 PM
 TIME OF BREAK: 12:00 Noon
 ENGINEER: Bernie Sears-Kuylt

LOCATION:
 GPS LOCATION: 8609 North Bahi Ct.

GPS: _____

PHOTO BEFORE REPAIRS:

Number of Pictures: None

SOIL CHEMISTRIES:

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type: Clay Sand Silt Clay/sand BGC* Other

DETAILS:

Pipe Type: Cast Iron Ductile Iron Steel PCCP Plastic
 Pipe Size: 6"
 Repair Method: Clamp Weld Cut Other


DETAILS:

Form of Break: Circular Longitudinal Other

DETAILS:

PHOTO AFTER REPAIRS:

Number of Pictures: None



* BGC = blue/gray clay