## **Howard County Traffic Signal Inspection Summary Report:**

**Signal Number:** 007

**Location:** Cedar Lane at Hickory Ridge Rd.

**Inspection Date:** April 11, 2018

**Inspection Overall Score:** 56

## Significant Findings:

NW Corner structure has significant rusting and deterioration around the base plate area, anchor bolts, and tightening nuts. Structural evaluation was completed, and media blasting, prime, and re-paint was recommended. NE Corner structure also has rusting and deterioration in the same areas, although not as severe.





## Maintenance Issues:

Electrical service has damaged conduit.

