

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 8: Am 6.8.2010
 TIME: 10: 50
 TIME OF BREAK: _____
 ENGINEER: ~~4015 Overlook Dr G1~~ Robison

LOCATION: _____
 GPS LOCATION: 4015 ~~Overlook~~ Overlook

GPS: 11 W

PHOTO BEFORE REPAIRS:

Number of Pictures: _____

SOIL CHEMISTRIES:

| REDOX | | SOIL BOX RESISTIVITES | | pH | |
|----------------------|--|-----------------------|--|----------------------|--|
| (mV) | | (Ohm-cm) | | (mV) | |
| (mV) | | (Ohm-cm) | | (mV) | |
| Top of Pipe (12) | | Top of Pipe (12) | | Top of Pipe (12) | |
| Side of Pipe (3 / 9) | | Side of Pipe (3 / 9) | | Side of Pipe (3 / 9) | |
| Bottom of Pipe (6) | | Bottom of Pipe (6) | | Bottom of Pipe (6) | |
| | | | | Actual Soil pH | |

Soil Type: ___ Clay ___ Sand ___ Silt Clay/sand ___ BGC* ___ Other

DETAILS:

Pipe Type: Cast Iron ___ Ductile Iron ___ Steel ___ PCCP ___ Plastic

Pipe Size: _____

Repair Method: Clamp ___ Weld ___ Cut ___ Other

DETAILS:

Form of Break: ___ Circular ___ Longitudinal Other

DETAILS:

PHOTO AFTER REPAIRS:

Number of Pictures: _____

| | |
|---|--|
| <p>SKETCH OF SITE</p> <div style="border: 1px solid black; height: 100px; width: 100%;"></div> | <p style="text-align: center;">TESTING VIEW</p> |
|---|--|

* BGC = blue/gray clay