65989

Entered (FP)

## HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY:	1.16.11					
TIME:					_	
TIME OF BREAK:	1:00			TALLETT		
ENGINEER:				T. PICKETT	-	
LOCATION:						
GPS LOCATION:		5633 ()-	1.11			
010200711011.		5033 On	enara wa	enc.		
		GRIDER	Br	2844 CONTRACT	64.11	
GPS.		- Niels.		Edit Comtained	E . W	
	•					
PHOTO BEFORE RE	EPAIRS:					
Number of Pictures:		• •			*	
SOIL CHEMISTRIES	:					
REDOX		SOIL BOX RESISTIVITES		рН		
	(mV)		(Ohm-cm)			
	(mV)		Ohm-cm)		(mV)	
Top of Pipe (12)	(1117)	Top of Pipe (12)	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Top of Pipe (12)	(1.77)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)		
Detterm of the (o)		30((0))		Actual Soil pH		
Soil Type: Cla DETAILS:						
Pipe Type:Cas Pipe Size:8"	st Iron	Ductile Iron	Steel _	PCCP Plast	ic	
Repair Method:	Clamp	Weld Cut	Oth	ner		
DETAILS:						
	· · · · · · · · · · · · · · · · · · ·					
Form of Break: /. DETAILS:	Circular	Longitudinal	Other			
PHOTO AFTER REPA	AIRS:					
Number of Pictures:	AII (O.					
Number of Fictures.			ī	TESTING VIEW		
SKETCH OF SITE				ILOTINO VIL		
SKETCH OF SHE				40	Тор	
			}	12		
			1			
			1	9	3	
			}		1	
		9	ļ	6	1	
				Clock		