

Howard County Pipe Break Field Data

| Location and Contact information | | | |
|----------------------------------|--|---------------------|-------------|
| Date | April 6, 2012 | Time | 03:00 |
| Crew Leader name | Chuck Barrett | Crew Leader phone # | 410-33-4900 |
| Address | 6607 Aspen Drive Elkridge, MD 21075 | | |
| ADC page | 4936 | ADC Grid | D10 |
| Base Map # | 2444 | Contract # | 950 |

Soil Type

| Type | Check box | Type | Check box |
|------|-----------|----------------|-------------------------------------|
| Clay | | Clay/sand | <input checked="" type="checkbox"/> |
| Sand | | Blue/gray clay | |
| Silt | | | |

Pipe Type

| Type | Check box | Type | Check box |
|--------------|-------------------------------------|----------------------|-----------|
| Cast iron | <input checked="" type="checkbox"/> | PCCP/Concrete | |
| Ductile iron | | Plastic PVC | |
| Steel | | Plastic polyethylene | |
| AC/Transite | | | |

Type of Break

| Type | Check box | Type | Check box |
|--------------|-----------|------------------|-------------------------------------|
| Circular | | Damage by others | |
| Split | | Pipe Joint leak | |
| Fitting leak | | two holes | <input checked="" type="checkbox"/> |

Size of Pipe
 Size in inches | 8

Repaired with # 0902 Full circle long range clamp (20" long)