## Howard County Pipe Break Field Data

	Location and Contact information				
Date	12-3-12		Time	700	
Crew Leader name	Ba //		Crew Leader phone #	1/3	
Address	6613	AllVIEW	Dr		
ADC page		ADC G	rid		
Base Map #		Contra	act #		

Soil Type

Туре	Check box	Туре	Check box
Clay		Clay/sand	V
Sand		Blue/gray clay	
Silt			

Pipe Type

Туре	Check box	Type	Check box
Cast iron	-	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Туре	Check box	Туре	Check box
Circular	V	Damage by others	
Split		Pipe Joint leak	
Pitting		Valve problem	
Fitting leak			

Size of Pipe

Size in inches	6
	_