

Howard County Pipe Break Field Data

Location and Contact information			
Date	12/3/2012	Time	8:00 am
Crew Leader name	Dave Ball	Crew Leader phone #	410-440-4782
Address	6613 Allview drive Columbia md 21045		
ADC page	4935	ADC Grid	C10
Base Map #	2440	Contract #	886

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	
Silt	x		

Pipe Type

Type	Check box	Type	Check box
Cast iron	x	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular	x	Damage by others	
Split		Pipe Joint leak	
Pitting		Valve problem	
Fitting leak		Clamp repair	

Size of Pipe

Size in inches	6"
----------------	----