66603

Entered (TP)

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY:					
TIME:	7				
TIME OF BREAK:	1:00				
ENGINEER:				T. PICKETT	_
LOCATION:					
GPS LOCATION:		(94)	1-1	No. 1	
0.000711011.		6942 Spinney Seed			
		CONTRACT 536	6A10-42	BM- 2342	-
GPS:					_
*					
PHOTO BEFORE RI					
Number of Pictures:	1 	* •			
COUL CUENICE DIEC	(<u></u>				
SOIL CHEMISTRIES:		SOIL BOX RESIS	TIVITES	-11	
REDOX (m)(1)		THE SHEET GUIDANT IDEATH THEO DO THE COST, WHILE WAS AN ADDRESS OF THE COST, WHILE THE COST, W		рН	/) //
* .	(mV)		(Ohm-cm)		(mV)
T (10)	(mV)		(Ohm-cm)	Top of Dina (12)	(mV)
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)	<u> </u>	Bottom of Pipe (6) Actual Soil pH	
Soil Type: Cla DETAILS:					
Pipe Type : 🖊 Ca:					ic
Pipe Size: Repair Method :					
	Clamp	Weld Cut	Oth	ner	
DETAILS:					
Form of Break:/	. Circular	Longitudinal	Other	•	
DETAILS:					
PHOTO AFTER REP	AIRS:				
Number of Pictures:			_		
				TESTING VIEW	
SKETCH OF SITE					Тор
				12	
			1		1
				9	3
				6	
				Clock	
					1