

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 8/2/09
 TIME: 2:30 PM
 TIME OF BREAK: Service Saddle
 ENGINEER: Bernie Sausbaugh

LOCATION:
 GPS LOCATION: 9059 LambSkin

GPS: _____

PHOTO BEFORE REPAIRS:
 Number of Pictures:

SOIL CHEMISTRIES:

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type: Clay Sand Silt Clay/sand BGC* Other

DETAILS:

Pipe Type: Cast Iron Ductile Iron Steel PCCP Plastic AC pipe

Pipe Size: 6"

Repair Method: Clamp Weld Cut Other

DETAILS:


Form of Break: Circular Longitudinal Other

DETAILS:

Service saddle rotted away

PHOTO AFTER REPAIRS: yes

Number of Pictures: 3



* BGC = blue/gray clay