H	0	M	JΔ	R	n	CO	LIN	ITY:	PI	PF	RR	FAL	(5	_ F	IFI	\mathbf{D}	\mathbf{D}	ΔΤ	Δ
				11			UIN				\mathbf{D}	-	1.3	_				F-3	\sim

DAY: TIME: TIME OF BREAK: ENGINEER:	12:0	-2010 ntt					
LOCATION: GPS LOCATION:	9/9	O Vollmentra	usen l	20.	_		
GPS:					_		
PHOTO BEFORE R Number of Pictures:							
SOIL CHEMISTRIES	<u> </u>	SOIL BOX RESIS	TIVITES	рН			
NEDOX	(mV)		(Ohm-cm)				
	(mV)	4———————	(Ohm-cm)		(mV)		
Top of Pipe (12)	<u> </u>	Top of Pipe (12)		Top of Pipe (12)	T		
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)			
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)			
Soil Type: Class DETAILS: Case Pipe Size: & Case Repair Method: DETAILS:	st Iron	Ductile Iron	Steel	PCCP Plast			
Form of Break: Y DETAILS: PHOTO AFTER REPA		Longitudinal _	Other				
TVUITIDET OF FICTURES.			Г	TESTING VIE	W		
SKETCH OF SITE				9 12 9 6	Тор		