| HOWAF | RD CO | UNTY: PIPE B | REAK | S - FIELD DAT | ΓΑ |
|---|--------------|----------------------|----------|----------------------|----------|
| DAY: | | 11-6-06 | | | |
| TIME: | | 8:00 AM | | | _ |
| TIME OF BREAK: | | | | | _ |
| ENGINEER: | | | | | _ |
| LOCATION: GPS LOCATION: | 6301 | Martin x | 2/ | | _ |
| GPS: 435 | - DAIDQ | | | | _ |
| PHOTO BEFORE RE Number of Pictures: | | | | | |
| Number of Field 55. | ÷ | | | | |
| SOIL CHEMISTRIES | i: | | | _ | |
| REDOX | | SOIL BOX RESIST | | pН | |
| | (mV) | <u> </u> | (Ohm-cm) | | (mV) |
| | (mV) | | (Ohm-cm) | | (mV) |
| Top of Pipe (12) | | Top of Pipe (12) | | Top of Pipe (12) | |
| Side of Pipe (3 / 9) | | Side of Pipe (3 / 9) | | Side of Pipe (3 / 9) | |
| Bottom of Pipe (6) | | Bottom of Pipe (6) | | Bottom of Pipe (6) | |
| Soil Type: Cla DETAILS: Pipe Type: Cas | | | | | _ Other |
| Pipe Type:Cas Pipe Size: Repair Method: DETAILS: | Clamp | Weld Cut | Oth | ner | ic |
| Form of Break: DETAILS: | Circular | Longitudinal _ | Other | | |
| PHOTO AFTER REP | AIRS: | | | | |
| Number of Pictures: | | | | | |
| | | | | TESTING VIE | |
| SKETCH OF SITE | | | | 9 12 6 Clock | Top 3 |