

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 3-11-06
 TIME: 9:00 am
 TIME OF BREAK: 10:00 PM 3-10-06
 ENGINEER: G. Gibson

LOCATION:

GPS LOCATION: 1105 St/om LA Columbia

GPS: 637-

PHOTO BEFORE REPAIRS:

Number of Pictures:

SOIL CHEMISTRIES:

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type: Clay Sand Silt Clay/sand BGC* Other

DETAILS:

Pipe Type: Cast Iron Ductile Iron Steel PCCP Plastic *A.C.*

Pipe Size: 8"

Repair Method: Clamp Weld Cut Other

DETAILS:


Form of Break: Circular Longitudinal Other

DETAILS:

service saddle blew off

PHOTO AFTER REPAIRS:

Number of Pictures:



* BGC = blue/gray clay