

# HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 9-15-05  
 TIME: 9:00 am  
 TIME OF BREAK: N/A  
 ENGINEER: G. Gibson

LOCATION:  
 GPS LOCATION: 5408 Smooth Meadow Way

GPS: 477 nts

**PHOTO BEFORE REPAIRS:**

Number of Pictures:     

**SOIL CHEMISTRIES:**

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type:  Clay  Sand  Silt  Clay/sand  BGC\*  Other

**DETAILS:**

Pipe Type:  Cast Iron  Ductile Iron  Steel  PCCP  Plastic

Pipe Size: 3"

Repair Method:  Clamp  Weld  Cut  Other

**DETAILS:**

Form of Break:  Circular  Longitudinal  Other

**DETAILS:**

**PHOTO AFTER REPAIRS:**

Number of Pictures:     

<p><b>SKETCH OF SITE</b></p> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>	<p style="text-align: center;"><b>TESTING VIEW</b></p> <div style="text-align: center;"> </div>
---	---

\* BGC = blue/gray clay