

Howard County Pipe Break Field Data

Location and Contact information			
Date	11/15/12	Time	
Crew Leader name	Dave Buzzell	Crew Leader phone #	410-313-4960
Address			
ADC page	4616	ADC Grid	45, B5
Base Map #	3343	Contract #	474 WAS

Soil Type

Type	Check box	Type	Check box
Clay	<input checked="" type="checkbox"/>	Clay/sand	
Sand	<input checked="" type="checkbox"/>	Blue/gray clay	
Silt	<input checked="" type="checkbox"/>	Debris	<input checked="" type="checkbox"/>

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular		Damage by others	
Split	<input checked="" type="checkbox"/>	Pipe Joint leak	
Fitting leak		Valve problem	

Size of Pipe

Size in inches	8
----------------	---

Replaced 5 1/2' of cast iron pipe with aqco. Use two eight inch hymax couplings (sleeves). An eight inch full circle clamp with 1 1/4" ee and new 1 1/4" ear punches were used to reconnect 1 1/4" wllc.