

## Howard County Traffic Signal Inspection Summary Report:

**Signal Number:** 006  
**Location:** Harpers Farm Rd. at Cedar La.  
**Inspection Date:** 02/27/2018

**Inspection Overall Score:** 71

### Significant Findings:

Single mast-arm structure located on the SE corner has severe rusting and deterioration around the base of the pole in the area behind the tightening nut caps. In one area there was an approximate two inch diameter hole in the base of the pole directly above the base plate weld. This pole also has signs of vehicle impact damage.



### Maintenance Issues:

SW Corner – ped pole is loose.