

Howard County Pipe Break Field Data

T. PICKETT

	Location and Contact information		
Date	5-26-12	Time	8:00 AM
Crew Leader name	TOM MILLER	Crew Leader phone #	
Address	10300 SHAKER DR		
ADC page	5053	ADC Grid	A-1
Base Map #	G-42-2340	Contract #	0699

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	
Silt	✓		

Pipe Type

Type	Check box	Type	Check box
Cast iron	✓	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular	✓	Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

Size of Pipe

Size in inches	6"
----------------	----