

## Howard County Pipe Break Field Data

	Location and Contact information		
Date	2/22/11	Time	15:00
Crew Leader name	G. Gibson	Crew Leader phone #	x 4900
Address	4895 Montgomery Road Ellicott City, MD 21043		
ADC page	4936	ADC Grid	C3
Base Map #	2844	Contract #	64

### Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand	<input checked="" type="checkbox"/>	Blue/gray clay	
Silt	<input checked="" type="checkbox"/>		

### Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

### Type of Break

Type	Check box	Type	Check box
Circular		Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	<input checked="" type="checkbox"/>

### Size of Pipe

Size in inches	12
----------------	----

12" double disc valve - bonnet bolt failure

M. T. [Signature]