

Howard County Pipe Break Field Data

Location and Contact information			
Date	12-1-12	Time	2:00 pm
Crew Leader name	David Ball	Crew Leader phone #	410-313-4900
Address	5035 GREEN MOUNTAIN Cir		
ADC page	4935	ADC Grid	A-05
Base Map #	2740	Contract #	171

Soil Type

Type	Check box	Type	Check box
Clay	<input checked="" type="checkbox"/>	Clay/sand	<input type="checkbox"/>
Sand	<input checked="" type="checkbox"/>	Blue/gray clay	<input type="checkbox"/>
Silt	<input type="checkbox"/>		<input type="checkbox"/>

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	<input type="checkbox"/>
Ductile iron	<input type="checkbox"/>	Plastic PVC	<input type="checkbox"/>
Steel	<input type="checkbox"/>	Plastic polyethylene	<input type="checkbox"/>
AC/Transite	<input type="checkbox"/>		<input type="checkbox"/>

Type of Break

Type	Check box	Type	Check box
Circular	<input checked="" type="checkbox"/>	Damage by others	<input type="checkbox"/>
Split	<input type="checkbox"/>	Pipe Joint leak	<input type="checkbox"/>
Fitting leak	<input type="checkbox"/>	Valve problem	<input type="checkbox"/>

Size of Pipe

Size in inches	6"
----------------	----