

65994

Entered  
TP

# HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 1-15-11  
 TIME: 4:00-PM  
 TIME OF BREAK: 2:00-PM  
 ENGINEER: T. PICKETT

LOCATION:  
 GPS LOCATION: 5436 - Ring Dove Lane

CONT-477- GRID-30 BM-2791

GPS: \_\_\_\_\_

### PHOTO BEFORE REPAIRS:

Number of Pictures: \_\_\_\_\_

### SOIL CHEMISTRIES:

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

\*Soil Type: \_\_\_ Clay \_\_\_ Sand  Silt \_\_\_ Clay/sand \_\_\_ BGC\* \_\_\_ Other

### DETAILS:

Pipe Type:  Cast Iron \_\_\_ Ductile Iron \_\_\_ Steel \_\_\_ PCCP \_\_\_ Plastic  
 Pipe Size: 6"  
 Repair Method:  Clamp \_\_\_ Weld \_\_\_ Cut \_\_\_ Other

### DETAILS:

Form of Break:  Circular \_\_\_ Longitudinal \_\_\_ Other

### DETAILS:

### PHOTO AFTER REPAIRS:

Number of Pictures: \_\_\_\_\_

SKETCH OF SITE  	TESTING VIEW

\* BGC = blue/gray clay