

## Howard County Pipe Break Field Data

	Location and Contact information		
Date	9/2/11	Time	03:30 am
Crew Leader name	Chuck Barrett	Crew Leader phone #	x 4900
Address	5469 Gloucester Road Columbia MD 21044		
ADC page	4934	ADC Grid	J5
Base Map #	2739	Contract #	277

### Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	<input checked="" type="checkbox"/>
Sand		Blue/gray clay	
Silt			

### Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

### Type of Break

Type	Check box	Type	Check box
Circular	<input checked="" type="checkbox"/>	Damage by others	
Split		Pipe Joint leak	
Fitting leak			