

Howard County Pipe Break Field Data

Location and Contact information			
Date	4/9/12	Time	02:00
Crew Leader name	Tom Miller	Crew Leader phone #	410-313-4900
Address	6680 Pich Way Elkridge, MD 21075		
ADC page	11936	ADC Grid	E 10
Base Map #	2444	Contract #	950

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	
Silt		CR 6	<input checked="" type="checkbox"/>

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular		Damage by others	
Split		Pipe Joint leak	<input checked="" type="checkbox"/>
Fitting leak			