

Howard County Pipe Break Field Data

Location and Contact information			
Date	11/15/2012	Time	7:00 am
Crew Leader name	Mike fisher	Crew Leader phone #	301-401-4680
Address	6700 Freetown road Columbia Md 21046		
ADC page	5052	ADC Grid	K1
Base Map #	2440	Contract #	553 w&s

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	
Silt	x		

Pipe Type

Type	Check box	Type	Check box
Cast iron	x	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular	x	Damage by others	
Split		Pipe Joint leak	
Pitting		Valve problem	
Fitting leak			

Size of Pipe

Size in inches	12"
----------------	-----