

Howard County Pipe Break Field Data

Location and Contact information			
Date	12-24-11	Time	10:30
Crew Leader name	Tom Pickett	Crew Leader phone #	
Address	7018 McKinstry Dr		
ADC page		ADC Grid	47
Base Map #	2040	Contract #	548

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	
Silt	<input checked="" type="checkbox"/>		

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular	<input checked="" type="checkbox"/> @ SERVICE	Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

Size of Pipe

Size in inches	6"
----------------	----