

Howard County Pipe Break Field Data

Location and Contact information			
Date	10/17/12	Time	8:00 pm
Crew Leader name	Leo Dicka	Crew Leader phone #	410-313-4900
Address	8651 Tidesebb Court Columbia MD 21045		
ADC page	4935	ADC Grid	K6
Base Map #	2742	Contract #	466

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	✓
Sand		Blue/gray clay	
Silt		CR6	✓

Pipe Type

Type	Check box	Type	Check box
Cast iron	✓	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular		Damage by others	
Split	✓	Pipe Joint leak	
Fitting leak		Valve problem	

Size of Pipe

Size in inches	3
----------------	---

Repaired with 3x15 full circle clamp
#0906