

Howard County Pipe Break Field Data

| Location and Contact information | | | |
|----------------------------------|------------------------------|---------------------|--------------|
| Date | 12-11-11 | Time | 4:00 AM |
| Crew Leader name | Chuck GARNETT | Crew Leader phone # | 410-313-4944 |
| Address | 9195 Baltimore National PIKE | | |
| ADC page | 4815 | ADC Grid | H-6 |
| Base Map # | 32-42 | Contract # | 11-W |

Soil Type

| Type | Check box | Type | Check box |
|------|-------------------------------------|----------------|-----------|
| Clay | | Clay/sand | |
| Sand | <input checked="" type="checkbox"/> | Blue/gray clay | |
| Silt | | | |

Pipe Type

| Type | Check box | Type | Check box |
|--------------|-------------------------------------|----------------------|-----------|
| Cast iron | <input checked="" type="checkbox"/> | PCCP/Concrete | |
| Ductile iron | | Plastic PVC | |
| Steel | | Plastic polyethylene | |
| AC/Transite | | | |

Type of Break

| Type | Check box | Type | Check box |
|--------------|-------------------------------------|------------------|-----------|
| Circular | <input checked="" type="checkbox"/> | Damage by others | |
| Split | | Pipe Joint leak | |
| Fitting leak | | Valve problem | |

Size of Pipe

| | |
|----------------|----|
| Size in inches | 8" |
|----------------|----|