

## Howard County Pipe Break Field Data

Location and Contact information			
Date	12/3/2012	Time	8:00am
Crew Leader name	Leo Dickey	Crew Leader phone #	410-446-6317
Address	9949 Decatur road laurel md 20723		
ADC page	5169	ADC Grid	F3
Base Map #	1741	Contract #	1-W

### Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	
Silt	x		

### Pipe Type

Type	Check box	Type	Check box
Cast iron	x	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

### Type of Break

Type	Check box	Type	Check box
Circular	x	Damage by others	
Split		Pipe Joint leak	
Pitting		Valve problem	
Fitting leak		Clamp repair	

### Size of Pipe

Size in inches	6"
----------------	----