

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 8-16-2016
 TIME: 9:00 AM
 TIME OF BREAK: 7:00 AM
 ENGINEER: Lang, Leo Dickey

LOCATION:
 GPS LOCATION: Business Parkway + Roosevelt Blvd.
Contract 1946

GPS: _____

PHOTO BEFORE REPAIRS:

Number of Pictures: _____

SOIL CHEMISTRIES:

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type: ___ Clay ___ Sand ___ Silt Clay/sand ___ BGC* ___ Other

DETAILS:

Pipe Type: ___ Cast Iron ___ Ductile Iron ___ Steel ___ PCCP ___ Plastic AC pipe
 Pipe Size: 8"
 Repair Method: Clamp ___ Weld ___ Cut ___ Other


DETAILS:

Form of Break: ___ Circular ___ Longitudinal ___ Other

DETAILS: Transition coupling leaking.

PHOTO AFTER REPAIRS:

Number of Pictures: _____



* BGC = blue/gray clay