

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 12-14-04
 TIME: 2:30 pm
 TIME OF BREAK: 11 11
 ENGINEER: _____

LOCATION:
 GPS LOCATION: 5824 BELLANCA DR.

GPS: 158

PHOTO BEFORE REPAIRS:
 Number of Pictures: _____

SOIL CHEMISTRIES:

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type: ___ Clay Sand ___ Silt ___ Clay/sand ___ BGC* ___ Other

DETAILS:

Pipe Type: Cast Iron ___ Ductile Iron ___ Steel ___ PCCP ___ Plastic

Pipe Size: _____

Repair Method: ___ Clamp ___ Weld Cut ___ Other

DETAILS:

Form of Break: ___ Circular ___ Longitudinal Other



DETAILS:

8' split

PHOTO AFTER REPAIRS:

Number of Pictures: _____

SKETCH OF SITE



* BGC = blue/gray clay