

# HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 8-9-04  
 TIME: 9:00  
 TIME OF BREAK: \_\_\_\_\_  
 ENGINEER: \_\_\_\_\_

**LOCATION:**

GPS LOCATION: 8527 High Ridge Road

GPS: 9-W

**PHOTO BEFORE REPAIRS:**

Number of Pictures: \_\_\_\_\_

**SOIL CHEMISTRIES:**

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type: \_\_\_ Clay \_\_\_ Sand \_\_\_ Silt  Clay/sand \_\_\_ BGC\* \_\_\_ Other

**DETAILS:**

Pipe Type:  Cast Iron \_\_\_ Ductile Iron \_\_\_ Steel \_\_\_ PCCP \_\_\_ Plastic

Pipe Size: 8"

Repair Method:  Clamp \_\_\_ Weld \_\_\_ Cut \_\_\_ Other

**DETAILS:**


Form of Break: \_\_\_ Circular  Longitudinal \_\_\_ Other

**DETAILS:**

8" split! Drilled Holes on both sides of split

**PHOTO AFTER REPAIRS:**

Number of Pictures: \_\_\_\_\_



\* BGC = blue/gray clay