

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 11-15-06
TIME: 11:30 Am
TIME OF BREAK: 10:00 Am
ENGINEER: G. Gibson

LOCATION:
GPS LOCATION: 3422 Jay Court

GPS: 11-W

PHOTO BEFORE REPAIRS:

Number of Pictures:

SOIL CHEMISTRIES:

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type: Clay Sand Silt Clay/sand BGC* Other

DETAILS:

Pipe Type: Cast Iron Ductile Iron Steel PCCP Plastic

Pipe Size: 6"

Repair Method: Clamp Weld Cut Other

DETAILS:

Form of Break: Circular Longitudinal Other

DETAILS:

PHOTO AFTER REPAIRS:

Number of Pictures:

<div style="border: 1px solid black; padding: 2px; margin-bottom: 5px;">SKETCH OF SITE</div> <div style="height: 150px;"></div>	<div style="border: 1px solid black; padding: 5px; text-align: center;"> TESTING VIEW </div> <div style="text-align: center;"> </div>
--	--

* BGC = blue/gray clay