

LOCATION MAP






Figure 4. Location Map for Site 1

■ DACCO SCI, INC. ■ 10260 Old Columbia Road, Columbia Road, Columbia, MD 21046 ■





Date: 9/7/94

Time: 9:55AM - 12:40PM


Stray Current Shifts: 0.189µA; (DC Potential Shifts - 12mV)

Current through Pipe: 9.18mA

Comments: Very busy traffic intersections; nearby Amoco

service station; O'Donnell car dealership

Figure 5. Current Interference Tests for Site 1







Figure 6. Detailed Current Interference Test Results for Site 1 from 9:56AM - 10:30AM







Figure 7. Detailed Current Interference Test Results for Site 1 from 10:30AM – 11:03AM







Figure 8. Detailed Current Interference Test Results for Site 1 from 11:03AM – 11:30AM






Figure 9. Detailed Current Interference Test Results for Site 1 from 11:45AM – 12:19PM




Figure 10. Detailed Current Interference Test Results for Site 1 from 12:19PM – 12:38PM