HOWARD CO	UNTY: PIPE	BREAKS	- FIELD	DATA
16-15	-04			

DAY:	16-15	16-15-04					
TIME:	TME: 4:00						
TIME OF BREAK:	2:00				-		
ENGINEER:					-		
					-		
LOCATION:							
GPS LOCATION: 5	1417 3	mooth Meadou	U Way				
GPS: 477 m	£S .						
PHOTO BEFORE R	EPAIRS:						
Number of Pictures:							
rambor or rotaroo.							
SOIL CHEMISTRIES	3:						
REDOX		SOIL BOX RESISTIVITES		рН			
(mV)		(Ohm-cm)					
	(mV)		(Ohm-cm)		(mV)		
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	(1114)		
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)			
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)			
				Actual Soil pH			
Soil Type: Cla DETAILS:	yS	andSilt	Clay/sar	nd BGC*	Other		
Pipe Type: Ca	st Iron	Ductile Iron	Steel	PCCP Plastic			
Pipe Size: 6"							
Repair Method:	Clamp	Weld Cut	Oth	er			
DETAILS:							
F(D)	0: 1						
Form of Break: DETAILS:	Circular	Longitudinal _	Other				
PHOTO AFTER REP	AIRS.						
Number of Pictures:	AIITO.						
tamber of Frotares.			Г	TESTING VIEW	, ,		
SKETCH OF SITE T				TESTING VIEW			
SKETOTOT OTTE					Тор		
*				9 12)		
				last 6	/		
			1	Clock			