

# HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 11-14-03  
 TIME: 9:00 am  
 TIME OF BREAK: 8:00 am  
 ENGINEER: \_\_\_\_\_

LOCATION:  
 GPS LOCATION: 6752 Springing step

GPS: 553-W

PHOTO BEFORE REPAIRS:  
 Number of Pictures: \_\_\_\_\_

**SOIL CHEMISTRIES:**

REDOX		SOIL BOX RESISTIVITIES		pH	
	(mV)		(Ohm-cm)		(mV)
	(mV)		(Ohm-cm)		(mV)
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type:  Clay  Sand  Silt  Clay/sand  BGC\*  Other

**DETAILS:**

Pipe Type:  Cast Iron  Ductile Iron  Steel  PCCP  Plastic  
 Pipe Size: 8"  
 Repair Method:  Clamp  Weld  Cut  Other


**DETAILS:**

Form of Break:  Circular  Longitudinal  Other

**DETAILS:**

**PHOTO AFTER REPAIRS:**

Number of Pictures: \_\_\_\_\_



BGC = blue/gray clay