

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: Sunday, November 7, 2003
 TIME: _____
 TIME OF BREAK: 8:30 am
 ENGINEER: Matt Tucker

LOCATION: _____
 GPS LOCATION: _____

GPS: _____

PHOTO BEFORE REPAIRS:

Number of Pictures: _____

SOIL CHEMISTRIES:

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type: ___ Clay ___ Sand ___ Silt Clay/sand ___ BGC* ___ Other

DETAILS:

Pipe Type: Cast Iron ___ Ductile Iron ___ Steel ___ PCCP ___ Plastic
 Pipe Size: 8"
 Repair Method: Clamp ___ Weld ___ Cut ___ Other

DETAILS:

Form of Break: Circular ___ Longitudinal ___ Other Circular 1W

DETAILS:

South of US Rt 1 40' South of Whiskey Bottom Rd

PHOTO AFTER REPAIRS:

Number of Pictures: _____

SKETCH OF SITE

