

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 009
Location: Cedar Lane at Owen Brown Rd.
Inspection Date: April 11, 2018

Inspection Overall Score: 46

Significant Findings:

NE Corner – older pole in fair condition, with moderate rusting of the tightening nuts. All other poles are newer and in good condition.



Maintenance Issues:

N/A