

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 031
Location: Harpers Farm Rd. at Twin Rivers Rd.
Inspection Date: April 11, 2018

Inspection Overall Score: 46

Significant Findings:

Poles, and paint coating are in overall fair condition. SW Corner – pole has significant coating failure around the base plate area, with moderate rusting around the base plate and tightening nuts. Recommend media blasting, prime, and re-paint.



Maintenance Issues:

Crosswalks and stop line are in fair condition.