

Howard County Traffic Signal Inspection Summary Report:

Signal Number: 064
Location: Dobbin Rd. at Old Dobbin Rd./Columbia Crossing
Inspection Date: April 12, 2018

Inspection Overall Score: 21

Significant Findings:

Poles and paint coating in overall good condition. One small area of paint coating failure and surface rusting on the pole on the NW corner. Recommend clean, prime, and re-paint.



Maintenance Issues:

NW and SE Corners – loose tightening nuts.