

Howard County Pipe Break Field Data

T. PICKETT

	Location and Contact information		
Date	5-27-12	Time	10:00 AM
Crew Leader name	Leo Dickey	Crew Leader phone #	
Address	10300 SHAKER DR		
ADC page	5053	ADC Grid	A-1
Base Map #	GRID-42-2340	Contract #	587

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	
Silt	<input checked="" type="checkbox"/>		

Pipe Type

Type	Check box	Type	Check box
Cast iron		PCCP/Concrete	
Ductile iron	<input checked="" type="checkbox"/>	Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular		Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	<input checked="" type="checkbox"/>

Size of Pipe

Size in inches	6
----------------	---