

Ball, D. 9-8-09

HOWARD COUNTY: PIPE BREAKS - FIELD DATA

DAY: 9-8-09
TIME: _____
TIME OF BREAK: _____
ENGINEER: _____

LOCATION:
GPS LOCATION: 4309 Cross Country Dr.

GPS: _____

PHOTO BEFORE REPAIRS:
Number of Pictures: _____

SOIL CHEMISTRIES:

REDOX		SOIL BOX RESISTIVITIES		pH	
(mV)		(Ohm-cm)		(mV)	
(mV)		(Ohm-cm)		(mV)	
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
				Actual Soil pH	

Soil Type: ___ Clay ___ Sand ___ Silt Clay/sand ___ BGC* ___ Other

DETAILS:

Pipe Type: Cast Iron ___ Ductile Iron ___ Steel ___ PCCP ___ Plastic
Pipe Size: 8"
Repair Method: Clamp ___ Weld ___ Cut ___ Other

DETAILS:


Form of Break: Circular ___ Longitudinal ___ Other

DETAILS:

PHOTO AFTER REPAIRS:
Number of Pictures: _____

SKETCH OF SITE

Old clamp leaking replaced



* BGC = blue/gray clay