

Howard County Pipe Break Field Data

	Location and Contact information		
Date	1-21-12	Time	3:00 pm
Crew Leader name	LEO Dickey	Crew Leader phone #	410-313-4900
Address	4802 Rolling Top Rd		
ADC page	4936	ADC Grid	E-2
Base Map #	28-44	Contract #	64-W

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	
Sand		Blue/gray clay	
Silt	<input checked="" type="checkbox"/>		

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular	<input checked="" type="checkbox"/>	Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

Size of Pipe

Size in inches	8"
----------------	----