HOWAI	RD CO	UNTY: PIPE E	BREAK	S - FIELD DA	TA
DAY:	1-2	-11			
TIME:		The state of the s			
TIME OF BREAK:					_
ENGINEER:					_
LOCATION: GPS LOCATION:	530	1 Fort x	Pel		-
GPS: 64-4	/				-
PHOTO BEFORE RI	EPAIRS:				
Number of Pictures:	·				
SOIL CHEMISTRIES);				
REDOX		SOIL BOX RESISTIVITES		ρΗ	
¥	(mV)		(Ohm-cm)		(mV)
	(mV)		(Ohm-cm)		(mV)
Top of Pipe (12)		Top of Pipe (12)		Top of Pipe (12)	
Side of Pipe (3 / 9)		Side of Pipe (3 / 9)		Side of Pipe (3 / 9)	
Bottom of Pipe (6)		Bottom of Pipe (6)		Bottom of Pipe (6)	
			/	Actual Soil pH	
Soil Type: Cla	y S	andSilt	_Clay/san	d BGC*	Other
DETAILS:				a.	
Pipe Type: Cas	st Iron _	Ductile Iron	Steel	PCCP Plast	ic
Pipe Size. 611	/				
Repair Method: 🔻	Clamp	Weld Cut	Oth	er	
DETAILS:					
	/				
Form of Break:	Circular	Longitudinal _	Other		
DETAILS:					
PHOTO AFTER REPA	AIRS:				
Number of Pictures:					
				TESTING VIE	W
KETCH OF SITE					Тор
				12	
				9 6	3
			I.	Clock	1