

Howard County Pipe Break Field Data

	Location and Contact information <i>5510 Hill Fall Ct, Columbia</i>		
Date <i>9-29-12</i>		Time <i>1:00PM</i>	
Crew Leader name <i>Bernie Sensibaugh</i>		Crew Leader phone # <i>410-313-4948</i>	
Address			
ADC page <i>4935-K5</i>		ADC Grid	
Base Map # <i>Grid# 30 - 2743</i>		Contract # <i>358 W+S</i>	

Soil Type

Type	Check box	Type	Check box
Clay	<input checked="" type="checkbox"/>	Clay/sand	
Sand		Blue/gray clay	
Silt	<input checked="" type="checkbox"/>	<i>Sand stone Rock</i>	<input checked="" type="checkbox"/>

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular	<input checked="" type="checkbox"/>	Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

Size of Pipe

Size in inches	<i>6"</i>
----------------	-----------

