

Howard County Pipe Break Field Data

Location and Contact information			
Date	11/14/12	Time	07:40
Crew Leader name	Tom Miller	Crew Leader phone #	410-313-4900
Address	5535 Green Mountain Circle Columbia MD 21044		
ADC page	4935	ADC Grid	5A, 5B
Base Map #	2740	Contract #	171

Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	<input checked="" type="checkbox"/>
Sand		Blue/gray clay	
Silt			

Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

Type of Break

Type	Check box	Type	Check box
Circular	<input checked="" type="checkbox"/>	Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

Size of Pipe

Size in inches	6
----------------	---

Repaired with Full Circle six-inch plain clamp #0841