

## Howard County Pipe Break Field Data

Location and Contact information			
Date	3-3-11	Time:	7:00
Crew Leader name	D. Ball	Crew Leader phone #	4900
Address	5576 Oakland Mill Rd		
ADC page	4935 F5	ADC Grid	2741
Base Map #		Contract #	295

### Soil Type

Type	Check box	Type	Check box
Clay		Clay/sand	<input checked="" type="checkbox"/>
Sand		Blue/gray clay	
Silt			

### Pipe Type

Type	Check box	Type	Check box
Cast iron	<input checked="" type="checkbox"/>	PCCP/Concrete	
Ductile iron		Plastic PVC	
Steel		Plastic polyethylene	
AC/Transite			

### Type of Break

Type	Check box	Type	Check box
Circular	<input checked="" type="checkbox"/>	Damage by others	
Split		Pipe Joint leak	
Fitting leak		Valve problem	

### Size of Pipe

Size in inches	8
----------------	---

underside work